



Offset Frontal Collisions and the Effect on Opposite Side Occupants

Using Crash Data to Identify People with
Critical Injuries that are Difficult to Detect

Jeffery Augenstein, Kennerly Digges,
James Stratton, Elana Perdeck

The William Lehman Injury Research Center

University of MIAMI



Outline

- Validation of URGENCY Algorithm to Detect Severe Injuries
- Corrections in Algorithms due to Offset Crashes
- Examples of injuries in Offset Crashes

University of MIAMI




Definition of Automatic Crash Notification (1st Generation)

- Identifies that a Crash Has Occurred
- Identifies the Crash Location
- Automatically Transmits the Information to a Third Party Who Dispatches Assistance

University of MIAMI



Automatic Crash Notification



University of MIAMI



Crash Signal Information

NHTSA/Calspan ACN System

- Delta-V
- Principal Direction of Force (PDOF)
- Rollover Indicator/Counter
- Travel Speed
- Vehicle Data (VIN Related)
- *2-Way Voice Communications*

University of MIAMI

Crash Vehicle Location

NHTSA/Calspan Automated Collision Notification System

File View Agencies Locate Incident Help



504

Crash Information

Time of Crash

Crash Date: 11/19/98
Crash Time: 1:55:00 PM
Elapsed Time: 0 days 00:01:52

Impact Details:

Lat/Long: N 42 56' 12.88" / W 78 42' 19.44"
Position Error: 1.08 m



Final Resting Position:


Left Side

Rollover



Change in Velocity = **38 mph**

504: 4905 Genesee St., Erie FIRE DISTRICT: Hy-View



Communications

Vehicle	Fax	Voice	Call status	Hold	Prerec
Vehicle					
Dispatcher					
Cheektowaga Police					
Cheektowaga Fire					
ECMC					
Manual Dial:					
Manual Dial:					

Vehicle Information - 7164802923

Vehicle | Owner | Likely Occupants

Make: Ford
Model: Taurus
Color: Blue
Year: 1994
Plate: 123456

Incident:504



Thursday November 19 1998, 1:56:52 PM

URGENCY Estimate of Serious Injury Probability

NHTSA/Calspan Automated Collision Notification System

File View Agencies Locate Incident Help



504

Crash Information

Time of Crash

Crash Date: 11/19/98
Crash Time: 1:55:00 PM
Elapsed Time: 0 days 00:06:03

Impact Details:


Lat/Long: N 42 56' 12.88"/W 78 42' 19.4"
Position Error: 1.08 m



Final Resting Position:
Left Side
Rollover

Change in Velocity = 38

504: 4905 Genesee St., Erie FIRE DISTRICT: Hy-View



Post Crash Algorithm: Injury Probability

File Data Help

Vehicle / Crash Data

Clear Data

RollOver: Yes

Crash Delta V (mph): 38


Side Damage, Passenger Compartment: No

Rear Damage: No

Curb Weight (lbs): 3200

Incident ID: 504

Estimate of Injury Probability



89%

Read IVM Data

Override IVM

Exit

Occupant Data

Clear Data

Seat Belt Used: No

Age: 30

Gender: Female

Entrapment: No

Complete Ejection: No

Communications

Vehicle

Dispatcher

Cheektowaga Police

Cheektowaga Fire

ECMC

Manual Dial:

Manual Dial:

Fax

Voice C

Year: 1994

Plate: 123456

Incident:504



Thursday November 19 1998, 2:01:03 PM



URGENCY Predictors of Injury

- Delta V & PDOF
- Rollover
- Belt Use
- Single Vs. Multi-vehicle Crash
- Extent of Damage
- Ejection & Entrapment
- Age & Gender
- Vehicle Weight

University of MIAMI



Injury Predictor Algorithm

Probability of Injury (P) Using Logistic Regression Analysis with Weighting Factors

$$P = 1/[1 + \exp(-w)]$$

$$w = A_0 + A_1 * \text{Pred } 1 + A_2 * \text{Pred } 2 + \dots$$

A_0 = Intercept


A_n = Coefficient

Pred n = Value of Predictor

University of MIAMI


Principle of Maximum Likelihood

Probability of Shown Outcome Using Car Crash Severity



Probability of
Casualty Levels
Using
DeltaV only

University of MIAMI



A_n for MAIS 3+ Injury Risk Binary Factors

Predictor	A
SINGLE	0.322
ROLL	1.157
GADSP	0.219
GADB	-1.793
OCCRE	-0.65
FEMALE	0.464
ENT	2.378
EJC	1.859

University of MIAMI

Source: Malliaris. SAE 970393, 1997



A_n for MAIS 3+ Injury Risk Continuous Variables


Predictor	A
TOTALDV	0.164
AGE	0.042
MAX CRUSH	0.037
CURBWT	-0.027

University of MIAMI

Source: Malliaris. SAE 970393, 1997



Sensitivity of Severe Injury to the Direction of Force, as a Function of Car Crash Severity



University of MIAMI



Application to Field Cases

- Frontal Crash
- Restrained Occupant
- 30 YO Male Driver
- 30 mph vehicle-to-vehicle crash
- 3200 Lb Car
- What is the probability of an AIS 3 Injury?

University of MIAMI



Baseline MAIS 3+ Injury Risk 3200 lb Car


Vehicular Crash Data Frontal Crashes

	Value	Data Check
DELTAV, in MPH?	30	
ROLL? (NO=0, YES=1)	0	TRUE
Single Vehicle? (NO=0, YES=1)	0	TRUE
Max Crush (in.)	22	
Car Curb Weight, in lbs.? (Default 3200 lbs.)	3200	
Air Bag + 3Pt Belt? (NO=0, YES=1)	0	TRUE
3 Pt Belt Only? (NO=0, YES=1)	1	TRUE
Car Occupant's Age, in years? (Default 30 yr.	30	
Occupant's Gender? (FEMALE=1, MALE=0)	0	TRUE
Entrapment? (NO=0, YES=1)	0	TRUE
Complete Ejection? (NO=0, YES=1)	0	TRUE
Partial Ejection? (NO=0, YES=1)	0	TRUE

Probability of Severe Injury

35%

Probability of MAIS 3+ Injury



Injury Risk

University of Miami




MAIS 3+ Injury Risk 2400 lb Car

Vehicular Crash Data Frontal Crashes

	Value	Data Check
DELTAV, in MPH?	30	
ROLL? (NO=0, YES=1)	0	TRUE
Single Vehicle? (NO=0, YES=1)	0	TRUE
Max Crush (in.)	22	
Car Curb Weight, in lbs.? (Default 3200 lbs.)	2400	
Air Bag + 3Pt Belt? (NO=0, YES=1)	0	TRUE
3 Pt Belt Only? (NO=0, YES=1)	1	TRUE
Car Occupant's Age, in years? (Default 30 yr.)	30	
Occupant's Gender? (FEMALE=1, MALE=0)	0	TRUE
Entrapment? (NO=0, YES=1)	0	TRUE
Complete Ejection? (NO=0, YES=1)	0	TRUE
Partial Ejection? (NO=0, YES=1)	0	TRUE

Probability of MAIS 3+ Injury



Injury Risk

Probability of Severe Injury **40%** University



MAIS 3+ Injury Risk 2400 lb Car (Belt+ Bag)


Vehicular Crash Data Frontal Crashes

	Value	Data Check
DELTAV, in MPH?	30	
ROLL? (NO=0, YES=1)	0	TRUE
Single Vehicle? (NO=0, YES=1)	0	TRUE
Max Crush (in.)	22	
Car Curb Weight, in lbs.? (Default 3200 lbs.)	2400	
Air Bag + 3Pt Belt? (NO=0, YES=1)	1	TRUE
3 Pt Belt Only? (NO=0, YES=1)	0	TRUE
Car Occupant's Age, in years? (Default 30 yr.)	30	
Occupant's Gender? (FEMALE=1, MALE=0)	0	TRUE
Entrapment? (NO=0, YES=1)	0	TRUE
Complete Ejection? (NO=0, YES=1)	0	TRUE
Partial Ejection? (NO=0, YES=1)	0	TRUE

Probability of Severe Injury

24%


Probability of MAIS 3+ Injury



Injury Risk



Sensitivity of Severe Injury to the Direction of Force, as a Function of Car Crash Severity



University of MIAMI



Validation of URGENCY Algorithm

Apply to WLIRC Cases with the Following Criteria:

- Frontal Crashes
- Belt + Air Bag

Cases that met Criteria

- 7 DOS
- 20 Met Physiological Triage (16 with MAIS 3+)(4 No)
- 30 Hi Suspicion of Injury (18 with MAIS 3+)(12 No)

University of MIAMI



URGENCY Validation - Baseline Prediction

	Low Risk	Med Risk	Hi Risk
Baseline	0-10	11-49	50+
DOS	0/	0/	7/
TRAUMA	8/	4/	8/
HISUS	8/	11/	11/

University of MIAMI



URGENCY Validation - Baseline Accuracy

	Low Risk	Med Risk	Hi Risk
Baseline	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	4/4	8/8
HI SUS	8/2	11/6	11/10

University of MIAMI



URGENCY Validation - Pole +

	Low Risk	Med Risk	Hi Risk
Baseline	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	4/4	8/8
HI SUS	8/2	11/6	11/10
Pole +	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	2/2	10/10
HI SUS	8/2	9/4	13/12

University of MIAMI




URGENCY Validation - Multiple Impacts

Pole +	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	2/2	10/10
HI SUS	8/2	9/4	13/12
Multiple	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	2/2	10/10
HI SUS	6/0	6/1	18/17

University of MIAMI

Frail Individual missed



URGENCY Validation - Close-in

Multiple	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	8/4	2/2	10/10
HI SUS	6/0	6/1	18/17
Close-in	0-10	11-49	50+
DOS	0/0	0/0	7/7
TRAUMA	4/0	1/1	15/15
HI SUS	6/0	6/1	18/17

University of MIAMI




Better Predictors - Frontals

- Pole Crashes at 20+ mph
- Multiple-impacts
- Close-in Occupants; Late deployments
- Other Factors
 - Frail Individuals
 - Complex Directions
 - Off-side Frontals

University of MIAMI



Off-side Frontals



University of MIAMI



Off-side Frontal (Driver)



University of MIAMI



Off-side Case


- Case 98-006BL
- 2-o'clock
- 9 mph Delta-V
- Fatal

University of MIAMI



9 mph Crash - Fatality

- 2 o'clock, 9 mph
- Restraints:
Lap & Shoulder Belt
Driver & Passenger
Air Bags Deployed




Case 98-006BL



9 mph Crash - Fatality

- 2 o'clock, 9 mph
- '93 Mercury Marquis



Case 98-006BL



9 mph Crash - Fatality

- Male Driver; 77 YO; 68" Tall; 272 Lbs
- Veh. - '93 Mercury Marquis
- POV- '97 Buick LeSabre
- 2 o'clock, 9 mph
- 10" Max Crush
- No Intrusion



Case 98-006BL



9 mph Crash - Fatality

Upper Body
Markings

Case 98-006BL





9 mph Crash - Fatality



Case 98-006BL



9 mph Crash - Fatality

- Trauma Criteria - Expired at Scene
- Restraints-
Lap & Shoulder
Belt
Air Bags Deployed



Case 98-006BL



9 mph Crash - Fatality

AIS-5 Brain Injury
Passenger Air Bag
Contact




University of MIAMI
Case 98-006BL



9 mph Crash - Fatality

- **Belt Induced Injuries:**
None
- **Other Injuries:**
AIS 5 - Brain
Passenger Air Bag



Left

Right

Case 98-006BL




Observations

- Shoulder Belt has Limited Effectiveness in Off-side Crashes
- Adjustments in URGENCY Algorithm May be Necessary



Past Studies Have Shown that
2-point Belts
Require Triage Criteria
Adjustment
in Far Side
Offset Frontal Crashes


University of MIAMI



Injury Risk- 3-Point Belts

Vehicular Crash Site Data	Value	Data	Serious Injury Risk
Damage to Left Front? (Left Front=1)	1	L. Front	<p>A bar chart with a vertical axis from 0% to 100% in 10% increments. A single red bar is shown at the 19% mark. The word 'Risk' is written below the bar.</p>
Damage to Center Front? (Center Front=1)	1	C Front	
Damage to Right Front? (Right Front=1)	0	NO	
Damage Greater Than 15"? (G.T. 15=1)	1	G.T. 15	
Damage Greater Than 25"? (G.T. 25=1)	1	G.T. 25	
Damage Greater Than 35"? (G.T. 35=1)	0	L.T. 35	
Single Vehicle Crash? (Single Vehicle=1)	0	MULTI.	
Rollover? (Rollover=1)	0	NO ROLL	
Entrapped or Ejected? (NO=0, YES=1)	0	NO	
Driver? (DRIVER=1, PASSENGER=0)	1	DRIVER	
Occupant's Gender? (FEMALE=1, MALE=0)	0	MALE	
Car Occupant's Age, in years? (Default 30 yr.)	30	TRUE	
Safety Belt Use? (NO BELT=0, YES, BELT=1)	1	YES	
Shoulder Belt Without Lap Belt? (NO LAP=1)	0	W LAP	
Probability of Severe Injury	19%		

University of MIAMI



Injury Risk 2-Point Belts

Vehicular Crash Site Data	Value	Data	Serious Injury Risk
Damage to Left Front? (Left Front=1)	1	L. Front	<p>A bar chart with a vertical axis from 0% to 100% in 10% increments. A single red bar is shown, reaching the 68% mark. The bar is labeled 'Risk' at the bottom.</p>
Damage to Center Front? (Center Front=1)	1	C Front	
Damage to Right Front? (Right Front=1)	0	NO	
Damage Greater Than 15"? (G.T. 15"=1)	1	G.T. 15	
Damage Greater Than 25"? (G.T. 25"=1)	1	G.T. 25	
Damage Greater Than 35"? (G.T. 35"=1)	0	L.T. 35	
Single Vehicle Crash? (Single Vehicle=1)	0	MULTI.	
Rollover? (Rollover=1)	0	NO ROLL	
Entrapped or Ejected? (NO=0, YES=1)	0	NO	
Driver? (DRIVER=1, PASSENGER=0)	1	DRIVER	
Occupant's Gender? (FEMALE=1, MALE=0)	0	MALE	
Car Occupant's Age, in years? (Default 30 yr.)	30	TRUE	
Safety Belt Use? (NO BELT=0, YES, BELT=1)	0	NO	
Shoulder Belt Without Lap Belt? (NO LAP=1)	1	NO LAP	
Probability of Severe Injury	68%		
			SUSPECT LIVER INJURY

University of MIAMI



Basis for Change in URGENCY

AAAM 2000 Paper by Augenstein,
et. al.



University of MIAMI



Population of Occupants

Restraint	NASS Belted (Exposed)	Lehman Belted (Injured)	Ratio
2- point	13%	32%	2.4
3-point	87%	68%	0.8



WLRIC- 48 Cases of Drivers with 2-Point Belts

Liver Injuries - 50%

From the Population with Liver Injuries:

Occult Liver Injuries - 78%

Mal-triaged Liver Injuries - 25%

University of MIAMI


Case 94-003 Shoulder Belt Only Right Flank Bruises



dV=19 mph

PDOF- 1 O'clock



Liver Injury-
AIS-4



University of MIAMI



Location of Liver and of Belt Marks



University of MIAMI



Undamaged Human Liver






Liver Laceration Caused by Belt Loading





96-035





All Case to Follow Had Liver Injuries of Type Shown

Injury Location



University of Miami



Belt Geometry Comparison



3-Pt Belt



2-Pt Belt
University of MIAMI



Characteristics of Liver Injury Cases

- Driver in 2 - Point Belt
- Right Front Vehicle Damage (Low Delta-V)
- Liver Injury on Right Rear Lobe

16 Cases to Follow

University of MIAMI



96-020 AIS-3 $dV=12$ mph

University of MIAMI



97-049
Air Bag

AIS-5

$dV=12$ mph

University of MIAMI



97-018

AIS-5

$dV=15$ mph

University of MIAMI



96-041
Air Bag

AIS 3

$dV=16$ mph

University of MIAMI



94-005
Air Bag

AIS-4

$dV=16$ mph

University of MIAMI



93-013 AIS-4 $dV=17$ mph

University of MIAMI



96-016

AIS-2

$dV=18$ mph

University of MIAMI



94-003

AIS-4

$dV=19$ mph

University of MIAMI



96-008

AIS-5 $dV=19$ mph

Fatal

University of MIAMI



96-012

AIS -5 $dV=19$ mph

Fatal

University of MIAMI



97-047

AIS-4

dV=19 mph

University of MIAMI



92-029

AIS-2

$dV=20$ mph

University of MIAMI



91-011

AIS-4

$dV=25$ mph

University of MIAMI



96-035

AIS-4

$dV=25$ mph

University of MIAMI



94-008

AIS-4

$dV=26$ mph

University of MIAMI



93-017

AIS-3

dV=27 mph

University of MIAMI



Are 3-point Belts Vulnerable to Injury in Off-side Crashes?

Case Studies from WLRIC

University of MIAMI



Driver and 3-Point Restraint

1 O'clock PDOF

University of MIAMI



Vehicle Damage

- Case Vehicle: 1988 Chevrolet Corsica
- PDOF: 1 O'clock
- DeltaV: 20.6 mph
- Max Crush: 12.5"
- Type: Frontal Offset
Vehicle to Vehicle

- POV: 1989 International
School Bus

Case #95-012





Occupant Information

- Case Subject: 70 Year Old Female
64" 125 lbs.
- Position: Driver
- Restraint: Lap and Shoulder
No Air Bag
- Admitted
LOS: 11 Days

Case #95-012





Injuries

Belt Restraint

- Contusion, Heart AIS-3
- Contusion, Chest, Right AIS-1
- Abrasion, Neck, Anterior AIS-1

Toe Pan

- Fx Malleolus, Left Posterior AIS-3
- Fx Malleolus, Left Medial AIS-2
- Fx Fibula, Left AIS-2
- Fx Fibula, Right AIS-2
- Fx Malleolus, Right Medial AIS-2

Case #95-012





Complications

- Heart Contusion In 70 Year Old Female
- Multiple Lower Extremity Fractures
Compounds Rehabilitation For Elderly

Case #95-012

University of MIAMI



Case Significance

- Restraint System Too Stiff For Elderly
Results In Heart Contusion
- Good Outcome For Elderly Driver
Length Of Stay 11 Days
- Off-side Frontal Crash

University of MIAMI



Driver and 3-Point Restraint

1 O'clock PDOF

University of MIAMI



Vehicle Damage

- Case Vehicle: 1990 Nissan Pathfinder
- PDOF: 1 O'clock
- DeltaV: 26 mph
- Max Crush: 23"
- Type: Frontal Offset
Vehicle to Vehicle
- POV:
1987 Toyota Camry

Case #98-017





Occupant Information

- Case Subject: 49 Year Old Female
64" 170 lbs.
- Position: Driver
- Restraint: Lap and Shoulder
No Air Bag
- Admitted
LOS: 8 Days

Case #98-017





Injuries




Belt Restraint

- Fx Ribs, Right AIS-3
- Avulsion, Omentum AIS-3
- Tear, Small Intestine AIS-2
- Abrasions, Multiple AIS-1
- Contusions, Multiple AIS-1

Steering Wheel Rim

- Contusions, Multiple AIS-1

Case #98-017





Complications

- Multiple Right Sided Rib Fractures
- Abdominal Injuries From Lap Belt Loading

Case #98-017

University of MIAMI



Case Significance

- Incompatible Vehicle Impact
Case Vehicle Size Helped Driver In Severe Impact
- Restraint Geometry Unfavorable To Short, Obese Female
- Abdominal Injuries From Lap Belt Suggest It was Not Tight Over Iliac Crests
- Off-side Frontal Crash

University of MIAMI



Driver and 3-Point Restraint

1 O'clock PDOF

University of MIAMI



Vehicle Damage

- Case Vehicle: 1987 Buick Century
 - PDOF: 1 O'clock
 - DeltaV: 24 mph
 - Max Crush: 11"
 - Type: Frontal Offset
Vehicle To Vehicle
 - POV:
 - 1987 GMC Jimmy
- Case #98-046





Occupant Information

- Case Subject: 68 Year Old Female
59" 108 lbs.
- Position: Driver
- Restraint: Lap And Shoulder
No Air Bag
- Died In Resuscitation

Case #98-046





Injuries


Belt Restraint

- Laceration, Liver AIS-5
- Laceration, Vena Cava AIS-4
- Fx Ribs, Right AIS-3
- Laceration, Lung Right AIS-3
- Compression Injury
Lumbar Spine AIS-3
- Fx Lumbar Vertebra AIS-2

Steering Wheel Rim

- Fx Ribs, Left AIS-2
- Laceration, Lung AIS-3

Case #98-046





Complications

- Severe Chest Trauma In Elderly Female
- Severe Liver Laceration From Belt Loading
Liver Pulpified In Multiple Lobes

Case #98-046

University of MIAMI



Case Significance

- Restraint Geometry Unfavorable To Short Female
- Multiple Impact Crash Produced Increase Belt Load On Driver
- Moderate Impact With Fatal Results To Elderly Driver
- Off-side Frontal Crash

University of MIAMI



RF Passenger and 3-Point Restraint

11 O'clock PDOF

University of MIAMI



Vehicle Damage

- Case Vehicle: 1989 Oldsmobile 98
- PDOF: 11 O'clock
- DeltaV: 25 mph
- Max Crush: 33"
- Type: Frontal Offset
Barrier Impact

Case #98-011





Occupant Information

- Case Subject: 70 Year Old Female
62" 130 lbs.
- Position: Right Front Passenger
- Restraint: Lap And Shoulder
No Air Bag
- Admitted
LOS: 9 Days

Case #98-011





Injuries



Belt Restraint

- Fx Thyroid Cartilage AIS-2
- Fx Arytenoid Cartilage AIS-2
- Abrasions/Contusions, Multiple AIS-1

Toe Pan

- Fx Malleolus, Media, Left AIS-2
- Fx Fibula, Distal, Left AIS-2

Case #98-011





Complications

- Multiple Left Lower Extremity Injuries
- Neck Injuries From Belt Loading

Case #98-011

University of MIAMI



Case Significance

- Restraint Geometry Unfavorable To Short Female
Resulted In Neck Injury
- Barrier Impact Crash Produced Clockwise Rotation
Increased Belt Load On Right Front Passenger
- Moderate Speed Impact With Favorable Results For
Passenger
Discharged In 9 Days
- Off-side Frontal Crash

University of MIAMI




Conclusions

CIREN Data Needs to be
Used to Improve Injury
Prediction and Treatment

Crash Information Could
Improve Triage and
Outcome

Risk

89%



SUSPECT LIVER INJURY

University of MIAMI